

L Number	Hits	Search Text	DB	Time stamp
-	3816	((73/862.328,862.326,862.325,862.333,862.334,862.335,862.08) or (324/208,207.12,207.21) or (318/432,488,2)).CCLS.	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/04/21 12:19
-	2017	((73/862.328,862.326,862.325,862.333,862.334,862.335,862.08) or (324/208,207.12,207.21) or (318/432,488,2)).CCLS.) and (shaft rod bar)	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/04/21 12:20
-	729	((73/862.328,862.326,862.325,862.333,862.334,862.335,862.08) or (324/208,207.12,207.21) or (318/432,488,2)).CCLS.) and (shaft rod bar)) and magnet\$6.clm.	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/04/21 12:21
-	453	((73/862.328,862.326,862.325,862.333,862.334,862.335,862.08) or (324/208,207.12,207.21) or (318/432,488,2)).CCLS.) and (shaft rod bar)) and magnet\$6.clm.) and (track plate tooth teeth spur rotor)	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/04/21 12:22
-	184	((73/862.328,862.326,862.325,862.333,862.334,862.335,862.08) or (324/208,207.12,207.21) or (318/432,488,2)).CCLS.) and (shaft rod bar)) and magnet\$6.clm.) and (track plate tooth teeth spur rotor)) and (torque torsion)	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/04/21 12:22
-	112	((73/862.328,862.326,862.325,862.333,862.334,862.335,862.08) or (324/208,207.12,207.21) or (318/432,488,2)).CCLS.) and (shaft rod bar)) and magnet\$6.clm.) and (track plate tooth teeth spur rotor)) and (torque torsion)) and phase	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/04/21 12:22
-	90	((73/862.328,862.326,862.325,862.333,862.334,862.335,862.08) or (324/208,207.12,207.21) or (318/432,488,2)).CCLS.) and (shaft rod bar)) and magnet\$6.clm.) and (track plate tooth teeth spur rotor)) and (torque torsion)) and phase) and compar\$6	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/04/21 12:40
-	2	((73/862.328,862.326,862.325,862.333,862.334,862.335,862.08) or (324/208,207.12,207.21) or (318/432,488,2)).CCLS.) and (shaft rod bar)) and magnet\$6.clm.) and (track plate tooth teeth spur rotor)) and (torque torsion)) and phase) and compar\$6) and (malfunction\$4 brok\$4 break\$3 fail\$4) and ((malfunction\$4 brok\$4 break\$3 fail\$4) with (notif\$4 inform\$4 alert\$4 alarm\$4 warn\$4 report\$4 notic\$4))	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/04/21 12:57
-	42	((73/862.328,862.326,862.325,862.333,862.334,862.335,862.08) or (324/208,207.12,207.21) or (318/432,488,2)).CCLS.) and (shaft rod bar)) and magnet\$6.clm.) and (track plate tooth teeth spur rotor)) and (torque torsion)) and phase) and compar\$6) and (malfunction\$4 brok\$4 break\$3 fail\$4)	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/04/21 14:03
-	42	((73/862.328,862.326,862.325,862.333,862.334,862.335,862.08) or (324/208,207.12,207.21) or (318/432,488,2)).CCLS.) and (shaft rod bar)) and magnet\$6.clm.) and (track plate tooth teeth spur rotor)) and (torque torsion)) and phase) and compar\$6) and (malfunction\$4 brok\$4 break\$3 fail\$4) not "2002/0124663"	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/04/21 12:56
-	41	((73/862.328,862.326,862.325,862.333,862.334,862.335,862.08) or (324/208,207.12,207.21) or (318/432,488,2)).CCLS.) and (shaft rod bar)) and magnet\$6.clm.) and (track plate tooth teeth spur rotor)) and (torque torsion)) and phase) and compar\$6) and (malfunction\$4 brok\$4 break\$3 fail\$4) not "10/081518"	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/04/21 14:25
-	1	((73/862.328,862.326,862.325,862.333,862.334,862.335,862.08) or (324/208,207.12,207.21) or (318/432,488,2)).CCLS.) and (shaft rod bar)) and magnet\$6.clm.) and (track plate tooth teeth spur rotor)) and (torque torsion)) and phase) and compar\$6) and (malfunction\$4 brok\$4 break\$3 fail\$4) not "10/081518" and ((malfunction\$4 brok\$4 break\$3 fail\$4) with (notif\$4 inform\$4 alert\$4 alarm\$4 warn\$4 report\$4 notic\$4))	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/04/21 14:02
-	529	((power assist\$4 electric\$4) near4 (steer\$6)) and ((malfunction\$4 anomaly abnormal\$4 brok\$4 break\$3 fail\$4) near10 (notif\$4 inform\$4 alert\$4 alarm\$4 warn\$4 report\$4 notic\$4))	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/04/21 14:27
-	64	((power assist\$4 electric\$4) near4 (steer\$6)) and ((malfunction\$4 anomaly abnormal\$4 brok\$4 break\$3 fail\$4) near10 (notif\$4 inform\$4 alert\$4 alarm\$4 warn\$4 report\$4 notic\$4)).clm.	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/04/21 14:28

-	69	((power assist\$4 electric\$4) near4 (steer\$6)) and ((malfunction\$4 anomaly abnormal\$4 brok\$4 break\$3 fail\$4) with (notif\$4 inform\$4 alert\$4 alarm\$4 warn\$4 report\$4 notic\$4)).clm.	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/04/21 14:28
-	46	((power assist\$4 electric\$4) near4 (steer\$6)) and ((malfunction\$4 anomaly abnormal\$4 brok\$4 break\$3 fail\$4) near4 (notif\$4 inform\$4 alert\$4 alarm\$4 warn\$4 report\$4 notic\$4)).clm.	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/04/21 14:28
-	29	((power assist\$4 electric\$4) near4 (steer\$6)) and ((malfunction\$4 anomaly abnormal\$4 brok\$4 break\$3 fail\$4) near4 (notif\$4 inform\$4 alert\$4 alarm\$4 warn\$4 report\$4 notic\$4)).clm.) and compar\$5	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/04/21 14:28
-	15	((power assist\$4 electric\$4) near4 (steer\$6)) and ((malfunction\$4 anomaly abnormal\$4 brok\$4 break\$3 fail\$4) near4 (notif\$4 inform\$4 alert\$4 alarm\$4 warn\$4 report\$4 notic\$4)).clm.) and compar\$5) and (torque torsion rotat\$5).clm.	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/04/21 14:29
-	15	((power assist\$4 electric\$4) near4 (steer\$6)) and ((malfunction\$4 anomaly abnormal\$4 brok\$4 break\$3 fail\$4) near4 (notif\$4 inform\$4 alert\$4 alarm\$4 warn\$4 report\$4 notic\$4)).clm.) and compar\$5) and (torque torsion rotat\$5).clm.) not "10/081518"	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/04/21 14:41
-	14	((("5239490") or ("4774464") or ("5019776") or ("4939435") or ("4783998") or ("6094995") or ("4874053"))).PN.	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/04/21 14:56
-	2	((("5239490") or ("4774464") or ("5019776") or ("4939435") or ("4783998") or ("6094995") or ("4874053"))).PN.) and (notif\$4 inform\$4 alert\$4 alarm\$4 warn\$4 report\$4 notic\$4)	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/04/21 14:56
-	5	4939435.URPN.	USPAT	2004/04/21 14:58
-	4	(US-5218279-\$ or US-5469032-\$ or US-5691611-\$ or US-5194794-\$).did.	USPAT	2004/04/21 15:01
-	2	("3060360"   "3193744").PN.	USPAT	2004/04/21 15:01
-	1	"10/081518" and correct\$5 with phase	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/04/23 08:49
-	1	"10/081518" and correct\$5 with (phase difference shift\$5)	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/04/23 09:02
-	1	"10/081518" and (maxim\$4 and minim\$4) with (compar\$6 difference)	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/04/23 09:07
-	1	"10/081518" and correct\$5 with (phase signal)	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/04/23 09:02
-	1	"10/081518" and (maxim\$4 near4 minim\$4) with (compar\$6)	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/04/23 09:10
-	0	"10/081518" and (maxim\$4 with minim\$4) near6 (compar\$6)	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/04/23 09:10
-	1	"10/081518" and (maxim\$4 with minim\$4) with (compar\$6)	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/04/23 10:39
-	0	"2002/0124663"	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/04/23 10:39

-	35	"0124663"	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/04/23 10:41
-	42	"69121"	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/04/23 10:41
-	2	"69121" and "rotational angle detecting apparatus"	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/04/23 10:44
-	17	"rotational angle detecting apparatus".ti.	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/04/23 10:44
-	7	("4751978"   "4821604"   "5032996"   "5065324"   "5563790"   "6330522"   "6386052").PN.	USPAT	2004/04/23 10:57
-	0	6536293.URPN.	USPAT	2004/04/23 10:58
-	0	6536293.URPN.	USPAT	2004/04/23 10:58
-	7	("4751978"   "4821604"   "5032996"   "5065324"   "5563790"   "6330522"   "6386052").PN.	USPAT	2004/04/23 11:17
-	4	((("4750368") or ("4856334"))).PN.	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/04/28 10:18
-	1	"10/081518"	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/06/22 10:02
-	4	"09/718003"	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/06/22 10:02
-	22	"09/718003" "09/739820" "09/888680" "09/903810" "09/690810" "09/960499" "10/081518" "10/231150" "10/2311203" "10/368558" "10/388734" "10/444899" "10/445353" "10/668602" "10/694906"	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/06/22 10:04
-	10	((("6363797") or ("6513396") or ("6543571") or ("6554096") or ("6691820"))).PN.	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/06/22 10:05
-	27	("09/718003" "09/739820" "09/888680" "09/903810" "09/690810" "09/960499" "10/081518" "10/231150" "10/2311203" "10/368558" "10/388734" "10/444899" "10/445353" "10/668602" "10/694906" ) (((("6363797") or ("6513396") or ("6543571") or ("6554096") or ("6691820"))).PN.)	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/06/22 10:05
-	0	((("09/718003" "09/739820" "09/888680" "09/903810" "09/690810" "09/960499" "10/081518" "10/231150" "10/2311203" "10/368558" "10/388734" "10/444899" "10/445353" "10/668602" "10/694906" ) (((("6363797") or ("6513396") or ("6543571") or ("6554096") or ("6691820"))).PN.)) and (semiconductor near2 "MR")	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/06/22 10:06
-	2	((("09/718003" "09/739820" "09/888680" "09/903810" "09/690810" "09/960499" "10/081518" "10/231150" "10/2311203" "10/368558" "10/388734" "10/444899" "10/445353" "10/668602" "10/694906" ) (((("6363797") or ("6513396") or ("6543571") or ("6554096") or ("6691820"))).PN.)) and semiconductor	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/06/22 10:06